


# CNC Mill Standard Operating Procedure


## LIMITATIONS

- ❑ This checklist is only for 3-axis machining.



- ❑ The checklist is only meant for material ISO grade N, P, M. You can find the ISO grade of your material using the following link: <https://www.purdue.edu/bidc/wp-content/uploads/2021/08/ISOGrade.pdf>. ISO grade C or unknown materials are not allowed.

- ❑ Give the cross section of clamped stock below, the unclamped area B needs to be less than or equal to three times the clamped area A.

**Area A <= 3 x Area B**

- This checklist only covers HydroForce assembly.
- This checklist only covers Gepard 300. Here are the limitations on the stock y-size:




- Round stock, plate stock, organic stock, drill chuck, er collets, 4-axis machining, 5-axis machining, ISO K, S, H etc. require specialized one to one training.

**MACHINE SPECIFIC HAZARDS**

- Hands can be caught in the rotating spindle, rotating chip auger or moving chip belt.



- Hands can get pinched on tool load and vice jaws.




- The tools can cut your hands.




- ☐ Coolant can irritate your skin.



- ☐ Stock, tools and fixtures can be heavy.




## MACHINE CONTROLS




## PRE-FLIGHT

### Tool Assembly


❑ Open **TOOL LIBRARY** in Fusion 360.




❑ Navigate to tools for current document.



❑ Navigate to the current setup.




- Press **REMOVE UNUSED TOOLS** and accept the popup.




- Repeat the following procedures for the setup of each HydroForce tool:
  - Select tool in list so **INFO** bar on right populates with information.


- Check holder type under **HOLDER DESCRIPTION** and **HOLDER PRODUCT ID**.
- Check tool under **DESCRIPTION** and **PRODUCT ID** if necessary.



- Retrieve **TOOL HOLDER**, tool, and collet with tool's shank diameter. You may use the IDs to guide you.
- Place **TOOL HOLDER** in **TOOL STAND** such that rectangular cutouts mates with the **MATING RECTANGLE** on **TOOL STAND** and the **LOCK** audibly clicks.
- Verify that **SET SCREW** faces away from **TOOL STAND**.



- Check **LENGTH BELOW HOLDER** in tool library where you identified tool and holder.
- Set calipers to **LENGTH BELOW HOLDER**, and lock with screw above the dial.
- Insert **COLLET** into **TOOL HOLDER** such that it is fully seated (if applicable).
- Insert **TOOL** into collet.
- Verify that distance between **TOOL TIP** and **COLLET TOP** face is **LENGTH BELOW HOLDER** using calipers.




- Hold **TOOL** to prevent slipping in **COLLET**.
- Tighten **SET SCREW** using hex key with yellow handles until screw no longer turns.
- Pull **LOCK** and remove **TOOL HOLDER** from **TOOL HOLDER STAND**.
- Place **TOOL HOLDER** in tool rack on machine.

## Stock Assembly

Select the jaws for the Gepard 300.

- **FLAT JAWS:** Use when stock has machined parallel flats to clamp on.




- **SERRATED JAWS:** Use when stock has extruded sides to clamp on.



Change jaws if needed.

- Use a 4mm hex key to change the jaws.
- Turn the hex key clockwise.



- Nudge with a mallet to loosen jaw. **Keep jaws open or else your hands will pinch against the other jaw.**



- Clean the bottom surfaces and replace jaws.



- Turn the hex key counterclockwise until you feel slight resistance to tighten jaw.
- Clamping the stock.
  - Use 16mm socket to hand tighten.



- Set torque wrench to 60 ft.lb and tighten until you hear a click.



### Program Load

- Upload CAM from PC to **NETSHARE** folder in Fusion Team.
- Press **LIST PROGRAM**.
- Navigate to **NETSHARE** using **CURSOR**.
- Type program code using **NUM PAD** and press **F1 / SEARCH**.
- Press **ENTER**.
- Press **F2 / COPY**.
- Press **ENTER** twice to copy into memory.
- PUT STUFF HERE**
- Press **MEM** to view G-code.
- Ensure loaded program is accurate.

### **OPERATE**

- Press **CYCLE START / START FEED**. Hover hand over **FEED HOLD / STOP FEED**.
- Load tools based on instructions from control and tool numbers from CAM.
- Tools will probe automatically, notify supervising Peer Mentor if the control throws an error.
- Validate WCS.
- Validate tool length.
- Check CAM for the current toolpath and **know the trajectory**.
- Press **FEED HOLD / STOP FEED** if machine operation deviates from expected (breakages, abnormal loud sounds, etc.)
- Check tool

## **POST-FLIGHT**

- Hold tool
- Press black button to release tool
- Disassemble tool, return bits and holders to proper location

### **Stock Unloading**

- Use breaker bar to break torque on workholding
- Remove any added fixturing

### **Cleanup**

- Close coolant valve
- Press **Coolant** button
- Rinse chips off workholding and into chip auger
- Use air hose to wipe off coolant and any remaining stuck chips
- Press **Chip FWD** and use chip auger stick if necessary
- Press **Coolant** and **Chip STOP**

- Turn coolant valve back open
  
- Complete assigned 5-minute shop job at the end of your reservation.