


Manual Mill Standard Operating Procedure


LIMITATIONS

- This checklist is only for simple horizontal endmill operations with a tool diameter $\leq \frac{1}{2}$ " and drilling into a flat face with a tool diameter $\leq \frac{3}{8}$ "



- This checklist only covers cutting materials ISO grade N, P1-3.
 - Note: Grade C is banned for all use on this machine.
 - You can find your material ISO grade [here](#).
- Give the cross section of clamped stock below, the unclamped area B needs to be less than or equal to five times the clamped area A.


Area A \leq 5 x Area B



- Round stock, plate stock and organic stock requires specialized one on one training.

MACHINE SPECIFIC HAZARDS

- Hands can be caught in the rotating spindle



- Hands can get pinched during tool loading and in vice jaws.




- ❑ The tools can cut your hands.




- ❑ Coolant can irritate your skin.




- Stock and tools can be heavy.



- There is a slip hazard when using coolant from a spray bottle




MACHINE CONTROLS



MILL BASICS: MOVEMENT


When using a mill, the material is clamped into a vise or directly to the table. The table is moved so that the workpiece moves past a spinning cutter.

The table can move in 3 directions, called X, Y & Z.



- + Handwheels and power feeds move the table horizontally (X & Y).
- + Z crank moves the table vertically (Z).


- + Locks keep the table from moving.
 - Lock each axis that is not moving
 - Unlock an axis before moving it.



PRE-FLIGHT

Tool Assembly


- Put tool into tool COLLET or JACOBS CHUCK
 - a. NOTE: When inserting tool into JACOBS CHUCK, the chuck will need to be inserted into the machine and use the spindle break.
- Hold tool carefully away from CUTTING EDGE



- Slide tool into spindle aligning it with the groove
- Press the ADD TOOL/WHITE BUTTON to draw tool
- Release ADD TOOL/WHITE BUTTON once tool is drawn into place
- Let go of tool once it is secured
- Consult speeds and feeds chart for correct RPM, feeds and step over

Stock Setup

- Open vice jaws, clean out chips/coolant with a rag
- Determine PARALLELS sizing, place stock into vice



- Tighten vice jaws while tapping top of stock with a mallet to seat parallels
- Ensure stock is rigid in jaws, parallels are seated

Coolant Containment

- Ensure the coolant plug is properly tightened



OPERATE

Tool Height Zeroing

- Use X & Y HANDLES to align part over part,
- Place paper underneath tool
- Slowly lower tool in z-direction using the QUILL HANDLE while moving paper back and forth
- Stop tool once you cannot move the paper
- Lock the quill using the QUILL LOCK
- Zero Z

Milling

- Move tool to starting point of stock using HANDWHEELS
- Set tool step over based on speeds and feeds chart
- Lower tool using the QUILL HANDLE to appropriate Z height based on speeds and feeds chart
- Release EMERGENCY STOP and twist spindle to FORWARD/FOR to spin up the spindle.
- Turn spindle to appropriate speed using RPM CONTROL knob
- Turn on POWER FEED in direction of cut using knob to adjust to appropriate feed
- Continue cut until tool is clear of the stock
- Turn off POWER FEED then spindle after cut or before if machine operation deviates from expected
- Turn EMERGENCY STOP on

POST-FLIGHT

Tool Unloading

- Hold tool carefully away from CUTTING EDGE
- Press REMOVE TOOL/BLACK BUTTON to release tool
- Disassemble tool, return bits and holders to proper location
- Return table to center and a normal height

Stock Unloading

- Open vice
- Remove part

Coolant Cleanup

- Use a drip pan and remove the nut to drain coolant



- Replace the nut after draining
- Drain the drip pan into the Hazardous Waste Barell in High Bay



Cleanup

- Wipe large chips from machine using small brush
- Use shop vac to remove remaining chips
- Sweep chips off the floor into a dustpan and place in chip bag

- Mop floor if necessary
- Complete assigned 5-minute shop job at the end of your reservation.