


# ST20 Standard Operating Procedure

## LIMITATIONS

- ❑ This checklist is only for Turning Face, Drilling, Turning Profile Roughing (only OD), Turning Profile Finishing (only OD), Turning Chamfer, Turning Single Grove, Turning Part and Turning Chamfer.
- ❑ This checklist is only for automatic probing, manual probing is beyond the checklist.
- ❑ The checklist is only meant for material ISO grade N, P, M. You can find the ISO grade of your material using the following link: <https://www.purdue.edu/bidc/wp-content/uploads/2021/08/ISOGrade.pdf>. ISO grade C or unknown materials are not allowed.
- ❑ Stock diameter (D/Dia) needs to be  $\geq \frac{1}{4}$ " and  $\leq 3\frac{1}{4}$ ". The placement needs to respect the rules below:



This checklist only covers changing inserts and adding/removing solid drills. The tool holders should also be in the correct spots as shown in the table below. Anything out of this order is non-standard.

Tool Number	Tool Type
1	Right Hand – KenLoc – C Style
2	KM-50 Axial block for ER32 holders (solid carbide drills), DFR inserted drills, and boring bars
3	Right Hand – KenScrew – V Style
4	KM-50 Axial block for ER32 holders (solid carbide drills), DFR inserted drills, and boring bars
5	Left Hand – KenScrew – V Style
6	KM-50 Axial block for ER32 holders (solid carbide drills), DFR inserted drills, and boring bars
7	Right Hand – OD Threading
8	KM-50 Axial block for ER32 holders (solid carbide drills), DFR inserted drills, and boring bars
9	Right Hand – TopNotch – OD Groving
10	DO NOT USE
11	Right Hand – Beyond Evolution – OD Part Off
12	DO NOT USE

This checklist only covers LMC Standard.


Anything outside of these limitations like tailstock, live tooling, threading etc. require a supervisor or higher supervising to proceed.

## MACHINE SPECIFIC HAZARDS


- Hands can be caught in the rotating spindle or moving chip belt.



- Hands can get pinched on chuck jaws.



- The tools can cut your hands.




- ☐ Coolant can irritate your skin.



- ☐ Stock, tools and jaws can be heavy.




## MACHINE CONTROLS




## PRE-FLIGHT

### Jaw Assembly


- ❑ Use a 10mm hex **WRENCH** to remove the 2 **BOLTS** from each of the 3 **JAWS**. You may use the **JAW WRENCH** to keep the **JAWS** stationery.




- ❑ Clean the **BOLTS**, **T-NUTS**, **JAWS** and **SLOT** with a **RED RAG** and **COMPRESSED AIR**.




- ❑ Partially screw in the **BOLTS** into the **T-NUTS** through the **JAWS**. Ensure the **T-NUTS** are oriented as shown. There are 3 holes in the **JAWS**, use the **FRONT** holes if your stock diameter is  $\leq 2.3"$ . Otherwise use the **BACK** holes.




- ❑ Place **JAW** and **T-NUT** assembly in the slots. Ensure the orientation of the **T-Nut** is as shown (flat side out). Also make sure that the numbers between **SLOTS** and the **JAWS** match. Make the **BOLTS** finger tight so the assembly does not fall off.





□ Count the number of **TEETH** that are exposed. Use this equation to figure out how many **TEETH** need to be exposed. Negative values are shown in the image below. Ensure all **JAWS** have the exact same **TEETH** count exposed, if not resecure them to match.

$$\text{TOOTH NUMBER} = -7.8 * \text{STOCK DIAMETER} + 12.75$$




- 5 teeth

+5 teeth


□ Clamp the **STOCK** in the secured **JAWS** using a **FOOT PEDAL**.



- Look at the **INDICATOR** on **JAW #1** to ensure it is within the **CENTRAL BOX**. If not make **TEETH** adjustment.



- With the **STOCK** removed, tighten the **BOLTS** as much as the hex **WRENCH** will allow. You will need to use the **JAW WRENCH** to achieve this.



- ❑ You may clamp the **STOCK** now if your **STICK-OUT** is  $\leq 4.5"$ . If not, you will have to run the program without **STOCK** to probe all the tools and then re-post the program without tool probing and run it with the **STOCK** in the machine. When placing the **STOCK** ensure the placement matches CAD.


### Program Load

- ❑ Upload CAM from PC to **NETSHARE** folder in Fusion Team.
- ❑ Press **LIST PROGRAM**.


- Navigate to **NETSHARE** using **CURSOR**.
- Type program code using **NUM PAD** and press down arrow in the **UI CURSOR** to search for it.
- Press **ENTER**.
- Press **F2 / COPY**.
- Press **ENTER** twice to copy into memory.
- Press **MEM** to view G-code.
- Ensure loaded program is accurate.

### Insert Placement


- Open **TOOL LIBRARY** in Fusion 360.




- 
- Navigate to tools for current document.




- ☐ Navigate to the current setup.



- ☐ Press **REMOVE UNUSED TOOLS** and accept the popup.



- ❑ Select tool in list so **INFO** bar on right populates with information.
- ❑ Check tool under **DESCRIPTION** and **PRODUCT ID** if necessary.






- ❑ Find the **INSERT** in the **INSERT** drawers which match **PRODUCT ID**. Keep in mind the **ANSI** code describes the geometry (there may be different inserts with same geometry), the **GRADE** describes the material (there may be different inserts made with same material), the **SAP CODE** (7 digit numeric) is unique. **ANSI** (alpha numeric) with **GRADE** (alpha numeric) is also unique.

The information below may be useful in understanding the codes:

# ANSI CODE

CNMG120408FP

04		08						FP	
Thickness S		Corner Radius "Rc"		Hand of Insert (optional)		Cutting Edge (optional)		Chipbreaker (optional)	
symbol	thickness	symbol	corner radius	R	= Right hand	F	Sharp	F	= Sharp
mm	mm	mm	mm	L	= Left hand	E	Rounded	FF	= Fine Finishing
—	0,79	X0	0,04	N	= Neutral	T	Chamfered	MN	= Medium Negative
T0	1,00	01	0,1			S	Chamfered and Rounded	MR	= Medium Roughing
01	1,59	02	0,2			K	Double-Chamfered	RN	= Roughing Negative
T1	1,98	04	0,4			P	Double-Chamfered and Rounded	UN	= Universal Medium
02	2,38	06	0,8					FP	= Finishing Positive
03	3,18	12	1,2					MP	= Medium Positive
T3	3,97	16	1,6					RP	= Roughing Positive
04	4,76	20	2,0					RM	= Roughing Medium
05	5,56	24	2,4					RH	= Roughing Heavy
06	6,35	28	2,8					FW	= Finishing Wiper
07	7,94	32	3,2					MW	= Medium Wiper
9	9,52	00						PS	= Finishing Sharp
11	11,11	MD	round insert					MS	= Medium Sharp
12	12,70	—						RW	= Roughing Wiper

"D"	± Tolerance on "D"				± Tolerance on "B"				Class U Tolerance
	Class M Tolerance		Class U Tolerance		Class M Tolerance		Class U Tolerance		
	Shapes S, T, C, R, & W	Shape D	Shape V	Shapes S, T, & C	"D"	Shapes S, T, C, R, & W	Shape D	Shape V	Shapes S, T, & C
mm	mm	mm	mm	mm	mm	mm	mm	mm	mm
3,97	0,05	—	—	—	3,97	0,08	—	—	—
4,76	0,05	—	—	0,08	4,76	0,08	—	—	0,13
5,56	0,05	0,05	0,05	0,08	5,56	0,08	0,11	—	0,13
6,35	0,05	0,05	0,05	0,08	6,35	0,08	0,11	—	0,13
7,94	0,05	0,05	0,05	0,08	7,94	0,08	0,11	—	0,13
9,52	0,05	0,05	0,05	0,08	9,52	0,08	0,11	0,18	0,13
11,11	0,08	0,08	0,08	0,13	11,11	0,13	0,15	—	—
12,70	0,08	0,08	0,08	0,13	12,70	0,13	0,15	0,25	0,20
14,29	0,08	0,08	0,08	0,13	14,29	0,13	0,15	—	—
15,88	0,10	0,10	0,10	0,18	15,88	0,15	0,18	—	0,27
17,46	0,10	0,10	0,10	0,18	17,46	0,15	0,18	—	0,27
19,05	0,10	0,10	0,10	0,18	19,05	0,15	0,18	—	0,27
22,22	0,13	—	—	0,25	22,22	0,15	—	—	0,38
25,40	0,13	—	—	0,25	25,40	0,18	—	—	0,38
31,75	0,15	—	—	0,25	31,75	0,20	—	—	0,38

## ■ Grade • Beyond™ • Beyond™ Drive™

beyond beyond DRIVE™

K	C	P	M	25	B
Brand	Insert Material	Primary Workpiece Material (ISO 513)	Secondary Workpiece Material (optional)	Application Range	Future Upgrades (optional)
<b>K</b> = Kennametal		<p><b>P</b> Steel  <b>M</b> Stainless Steel  <b>K</b> Cast Iron  <b>N</b> Non-Ferrous  <b>S</b> High-Temp Alloys  <b>H</b> Hardened Materials  <b>U</b> Universal Machining</p>			<p><b>B</b> = Beyond™ Drive™  <b>C</b> = Generation 3 etc.</p>

**Blank** = Carbide, uncoated  
**C** = Carbide, coated  
**T** = Cermet  
**Y** = Ceramic  
**D** = PCD  
**B** = PcbN


**Hardest**


↑ 5 fine finishing  
10 finishing  
15 medium to roughing  
20  
25 roughing  
30  
35  
40  
45  
50 heaviest roughing

↓  
**Toughest**

NOTE: Application range does not apply to PcbN grades.

- Once you have acquired the correct **INSERT** compare it against the **INSERT** in the machine. If they match, then you can proceed to the next tool.
- If not, then change the **INSERT** as shown in the images below.







- ❑ While changing ensure you check to make sure the **SHIMS**, **SEATS** and **SCREWS** are in good condition.

### **Solid Drill Placement**


- ❑ Obtain **DESCRIPTION**, **PRODUCT ID** and **LENGTH BELOW HOLDER** from the **INFO** tab as shown above.
- ❑ Select an ER32 **COLLET** based on the diameter of the **SHANK**. The **COLLET** should never expand when you place your tool in it.



- ❑ Select a **COOLANT RING** for the tool. If the tool has no **TSC** capability use a ring that leaves an  $1/8"$  gap around the tool. Otherwise pick one that seals on the tool **SHANK**.
- ❑ Get a ring compatible ER32 **NUT**. Clean **SHANK**, **NUT**, **TAPER**, **COLLET** and **COOLANT RING**.



- ❑ Assemble as shown:



## OPERATE

- ❑ Press **CYCLE START / START FEED**. Hover hand over **FEED HOLD / STOP FEED**.
- ❑ Load tools based on instructions from above and tool numbers from CAM.

- Tools will probe automatically, notify Supervisor if the control throws an error.
- Check CAM for the current toolpath, before every operation, and **know the trajectory**.
- Press **FEED HOLD / STOP FEED** if machine operation deviates from expected  
(breakages, abnormal loud sounds, etc.)
- Check tools and parts after every operation.

## **POST-FLIGHT**

- Disassemble all solid drills and return **COLLET**, **COOLANT RING** and **TOOL**.
- Remove **STOCK**.
- Use **CUT GLOVES** to remove **LONG CHIPS** and place them in the **METAL SCRAPS**.



- Press **Chip FWD** and use chip conveyor if necessary.
- Mop up any coolant drops that might be on the floor.
- Complete assigned 5-minute shop job at the end of your reservation.