Homework Problem H25.A

Given: A machine is made up of links AD, BC, CE and DE, as shown below. Point A is pinned to ground, with B being constrained to move along a smooth horizontal surface in the direction of x. Loads F and P act at pins E and B, respectively.

Find: Determine the ratio of F/P needed for the machine to be in equilibrium.