

Quick Reference Card

PM Work Order Screens - Header

Process

This job aid highlights many of the key parts of the Work Order screen

The screenshot shows the SAP PM Work Order Header screen for 'Change REQUEST FOR SERVICES 900000328: Central Header'. The main description is '006-1061-7169 CREATE RETURN AIR PLENUM'. The status is 'REL PRT MANC NMAT PRC SETC'. The screen is divided into several tabs: 'HeaderData', 'Operations', 'Co...', 'Partner', 'Objects', 'Addit. Data', 'Location', 'Planning', and 'Control'. The 'HeaderData' tab is active, showing fields for 'Person responsible' (PlannerGrp 234), 'Mn.wk.ctr' (SHEETMTL / 4000), 'Requestor' (98101682), 'Mfnctn' (10000278), 'Costs' (0.00), 'PMActType' (003), and 'SystCond.'. Below this is the 'Dates' section with fields for 'Bsc start', 'Basic fin.', 'SchedStart', 'Sched.Fin.', 'SchedType', 'Rel. view', 'Version', 'Priority', 'Revision', 'Act. start', 'Actual end', 'RefDate', 'Start in past', and 'Adjust dates'. The 'Reference object' section shows 'Func. Loc.' (1000-WADM-1056) and 'LYTLE J. FREEHAFFER HALL OF ADMIN SERV'. At the bottom, the 'Malfnctn data' tab is active, showing 'Malfnctn start' (05/09/2006 15:22:09) and 'Malfnctn End' (00:00:00). A status bar at the bottom indicates 'Planner group does not exist in planning plant'.

Callouts:

- Main Description and Status section:** Points to the main description and status fields at the top of the screen.
- Required fields:** Points to the 'Person responsible' and 'Mn.wk.ctr' fields.
- Each tab views a different "set" of data. The first three tabs are used most often.** Points to the tabbed interface.

Quick Reference Card

Work Order Operations & Components

Process

This job aid highlights some of the more significant areas on the Operations and Component views of a Work Order.

Change REQUEST FOR SERVICES 900000328: Operation Overview

Order: RFS 900000328 006-1061-7169 CREATE RETURN AIR PLENUM

Sys.Status: REL PRT MANC NMAT PRC SETC

HeaderData | **Operations** | Components | Costs | Partner | Objects | Addit. Data | Location | Planning | Control

OpAc	SOp	Work ctr	Plant	Con...	StTextK	S...	Operation short text	LT	Work	Un	Nu...	Dura
0010		SHEETMTL	4000	PM01			006-1061-7169 CREATE RETURN AIR PLENUM			2H	1	
0020		SHEETMTL	4000	PM01			Drawing Date			H		
0030		SHEETMTL	4000	PM01						H		
0040		SHEETMTL	4000	PM01						H		
0050		SHEETMTL	4000	PM01						H		

General | Internal | External | Dates | Act. Data | Enhancement | Ex. Factor | Catalog

Watch for Long text providing more detail

Change REQUEST FOR SERVICES 900000328: Component Overview

Order: RFS 900000328 006-1061-7169 CREATE RETURN AIR PLENUM

Sys.Status: REL PRT MANC NMAT PRC SETC

HeaderData | Operations | **Components** | Costs | Partner | Objects | Addit. Data | Location | Planning | Control

Item	Component	Description	LT	Reqmnt Qty	UM	IC	S...	SLoc	Plnt	OpAc	Bat
0010											
0020											
0030											
0040											
0050											

Any parts ordered through SRM Component Planning would show up here