

DESIGN RULES FOR 3D PRINTING



	Supported Walls	Unsupported Walls	Support & Overhangs	Embossed & Engraved Details	Horizontal Bridges	Holes	Connecting /Moving Parts	Escape Holes	Minimum Features	Pin Diameter	Tolerance
	Walls that are connected to the rest of the print on at least two sides.	Unsupported walls are connected to the rest of the print on less than two sides.	The maximum angle a wall can be printed at without requiring support.	Features on the model that are raised or recessed below the model surface.	The span a technology can print without the need for support.	The minimum diameter a technology can successfully print a hole.	The recommended clearance between two moving or connecting parts.	The minimum diameter of escape holes to allow for the removal of build material.	The recommended minimum size of a feature to ensure it will not fail to print.	The minimum diameter a pin can be printed at.	The expected tolerance (dimensional accuracy) of a specific technology.
Fused Deposition Modeling	0.8 mm	0.8 mm	45°	0.6 mm wide & 2 mm high	10 mm	∅2 mm	0.5 mm		2 mm	3 mm	±0.5% (lower limit ±0.5 mm)
Stereolithography	0.5 mm	1 mm	support always required	0.4 mm wide & high		∅0.5 mm	0.5 mm	4 mm	0.2 mm	0.5 mm	±0.5% (lower limit ±0.15 mm)
Selective Laser Sintering	0.7 mm			1 mm wide & high		∅1.5 mm	0.3 mm for moving parts & 0.1 mm for connections	5 mm	0.8 mm	0.8 mm	±0.3% (lower limit ±0.3 mm)
Material Jetting	1 mm	1 mm	support always required	0.5 mm wide & high		∅0.5 mm	0.2 mm		0.5 mm	0.5 mm	±0.1 mm
Binder Jetting	2 mm	3 mm		0.5 mm wide & high		∅1.5 mm		5 mm	2 mm	2 mm	±0.2 mm for metal & ±0.3 mm for sand
Direct Metal Laser Sintering	0.4 mm	0.5 mm	support always required	0.1 mm wide & high	2 mm	∅1.5 mm		5 mm	0.6 mm	1 mm	±0.1 mm

<https://s3-eu-west-1.amazonaws.com/3dhubs-knowledgebase/key-design-considerations-for-3d-printing/3d-printing-design-rules-high-res.png>